G. R. S. 59] GPB—15,000 - 20 12 13

GENERAL AND REVENUE SECRETARIAT.

1894-95—
191.
(Miscellaneous)

File No. 112

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Passing a Completion bill for Rs 350-15-7 for repairing certain out Houses of the Sri Yoga-Narasimhaswamy Temple at Gorur, Hassan Taluk

PREVIOUS REFERENCES.	LATER REFERENCES.

(General Serial No. 29.)

1887. 6574

From



3824

To

The Chief Secretary to the Dewan of Mysore

Dated 10th December 1887

Despatched 11

Received

Enclosures No. 1 to 4

General No. 3232 Secy No. 398. } 1887. 88

Forwarding for sanction an estimate amounting to Rs 365- for restoring Kitchen and Gagosale of the Gopalaswamy temple at Sosur in the Srirangapatna Division.

To Assistant Commissioner

No. 398 Secy

Sm-1 & VMP.

Dated Wapam 10th December 1887

From.

P. N. Purnaniya Esqre
Dy Commissioner,
Wapam Dist.

To,

The Chief Secretary to the
Dewan of Mysore,

Sir,

I have the honor to submit herewith for the Sanction of the Dewan an Estimate amounting to Rs 365/ for restoring the Kitchen & Yagasala attached to Sri Yoganar-
-Sinhaswamy's temple at Gôrûr in the Wapam Taluk.-

2. The charge can be met from the Sum of Rs 629-14-0 at the disposal of this institution as per Treasury officer's certificate in the Estimate

3. The vernacular papers relating to the receipts of restoring the buildings are also submitted herewith for needful reference and obliging return.-

I have the honor to be,
Sir
Your most obt Servt
PNPurnaniya
Dy Commissioner Wapam

	Deduct for doors ———	3	×		2½	175	
	Balance ———						2847
Jungle	Doors with shutters						1.97
	Ins is on Complete ———	3	5	-	2	Ans	3
Slabs	For covering ———	11	6	1½	½	49	
	Jambs over doors ———	3	3½	1⅛	½	6	
	Slabs below door frame	3	3	1⅛	½	126	123
Dismantling	Old roof ———	1	66	15	1	990	
	North wall ———	1	60	1⅛	6	405	
	South —do—	1	40	1⅛	6	270	
	End + cross do	4	10	1⅛	6	270	
	Total						1935
Petty repairs	Air holes on the roof of cycle room ———					Ans 3	
	Removing the present big slab in the kitchen and replacing the saw with proper position						
	Dressing the present covering slabs and fitting them properly.					Lump	

Estimate of the probable cost of restoring the Mahatma Temple to be known as Ramakrishna Swamy Temple (Gopuram in the Hussain Pettah.

Items	Details	No	Dimensions L.	B.	D.	Contents	Total
Excavation	Foundation trench South wall	1	40	1½	1½	90	
	do North do	1	66	1½	1½	148	
	do End do	2	10	1½	1½	45	
	do Cross do	2	10	1½	1½	45	
	Total					328	12
Rough stone in clay Burnt brick in clay	Filling in earth Superstructure					328	
	South wall	1	40	1⅛	6	270	
	North do	1	66	1⅛	6	446	
	End do	2	10	1⅛	6	135	
	Cross do	2	10	¾	6	90	
	Cornice	1	152	1⅛	½	86	
	Parapet wall	1	152	¾	1	114	
	Total					1141	
	Deduct openings for doors	3	5	1⅛	2½	42	
	Balance						1099
Concrete	flooring	1	60	10	¼	150	
	roof	1	70	10	½	350	
	Total						500
Plastering with chunam	Inside the north wall	1	70	-	6	420	
	Both sides of North do	2	70	-	6	840	
	End walls	2×2	10	-	6	240	
	Cross do	2×2	10	-	6	240	
	Cornice	1	152	-	½	76	
	Parapet wall	1	152	-	¾	456	
	Total					2272	2272

Abstract

Details of items	Per	Rate	Quantity	Cost
Excavation	cyd	- 1 6	~~12~~ 24	1 2 - -
Rough stone in clay	cft	- 1 3	328	26 -
Burnt brick in clay	"	1 6	1094	103
Concrete	-	- 2 -	500	62 -
Plastering with Chunam	sqyrd	3 - -	~~21.97~~ 22	~~66~~ 87 -
Single wood doors with hinges hooks &c complete	No	10 - -	3	30 - -
Burnt slabs	sft	- 4 -	~~61~~ 23	~~15~~ 9 - -
Dismantling the present roof &c	cft	- - 1	1,935	10 - -
Petty repairs Air holes	each	5 - -	3	15 - -
Removing slabs &c.				10 - -
Dressing the present covering (slabs.			-	10 - -
Total		Rs	348	384
Contingency at 5 per cent			17	19 -
Grand Total			365	403

Rupees four hundred and five only.

Hussan
30th August 1887

K. Ramchandra
General Asstt Comr

I do hereby certify that Hussan Rs 280.1.3 and Rs 349.12.9 are in favor of this institution under the heads "Management" and "Savings Bank" respectively.

25 October 87.

Asstt Commr Northern Div
Incharge Officer
Hassan

Read:—

Letter No: 398 of the 10th instant from the Deputy Com^r of Hassan, submitting for sanction an Estimate for Rs: 365— for repairing certain outhouses of the Goja Narasimmaswamy's Temple at Gorur in the Hassan Taluk, the charge being met from Rs: 629-14— at its credit.

Order.

Sanctioned.

By
Secretary

To The Dy. Com^r, Hassan
Returning enclosures
" Comptroller with copy
of Abstract Estimate &
Treasury Officer's Certificate

(General Serial No. 31.) Draft

188

(1)

From

To The Dy Comr Customs
Comptroller

Dated 16 — 12 89

Despatched

Received

Enclosures No. 1 + 1 Papers

General No 5232-30
No. 179

(2) 53-9

Gen. Serial No. 30.]

1895

MUZARAI.

From

To Comr to Govt Hassan District.

Dated 12 "

Despatched 18 " Mareh 95

Received

Enclosures No. 1 2

General No. 829 / 820
Muzarai F. No.

Govt Pro No 5232-3 / 179 dy 16th Decr 1887 sanctioning an estimate amounting to Rs 365/- for repairing certain out-houses of the Yoga Narasimhaswamy temple Gowrisn the Hassan Taluk

---

With reference to the above has the honor to forward herewith a completion Bill for Rs 350-15-7, being

the actual cost incurred in carrying out the ~~aforesaid~~ similar repairs, and to request that the bill may be ~~may be~~ audited and forwarded to the Deputy Comm., Hassan District for payment.

By order

Secretary

No 8209 / 12/18/6/95

Copy forwarded to the Deputy Comm., Hassan Distt., for information with reference to his Rub-kari No 530 dy 4th March/95

By order

Secretary

C.Z.